Uttar Pradesh Medical Supplies Corporation Ltd.

Regd. Office: 7/23, sector-7, Gomti Nagar Extension, Lucknow-226002 Phone nos. 0522 2838102, e-mail:manager.it@upmsc.in

Letter No.: 2G8 /IT/UPMSCL/2023

Date: 21-10, 2023

NOTICE INVITING QUOTATION

Sealed Quotation is hereby invited from authorized service provider/authorized dealer for Inspection and repair of Faulty Laptops, Computers (CPU) and UPS from 21.10.23 to 31.10.23 at Uttar Pradesh Medical Supplies Corporation Ltd., Lucknow Headquarters. Sealed quotation in an envelope may be submitted at UPMSCL Headquarter, super scribed "Quotation for Repair of Computer Systems and UPS" The last date for submission of quotation is 31st Oct 2023 till 05:00 P.M.

Terms & Conditions:

1. The Location of Work will be UPMSCL Office H.Q., Lucknow.

Engineer shall visit the location for inspection of faulty items before submitting the sealed quotation.

 The Payment will be processed after submission of bills to UPMSCL office, Lucknow for successful repairing/ part replacement of the items at the destination.

4. UPMSCL reserves the right to cancel this NIQ at any time.

Attachment: Price Bid (Annexure-I), Item Details (Annexure-II)

> Manager IT (UPMSCL)

Copy to:

Managing Director, UPMSCL Lucknow

2. Finance Controller, UPMSCL Lucknow

3. GM Equipment, UPMSCL Lucknow

Manager IT (UPMSCL)

Uttar Pradesh Medical Supplies Corporation Ltd.

Regd. Office: 7/23, sector-7, Gomti Nagar Extension, Lucknow-226002
Phone nos. 0522 2838102, e-mail:manager.it@upmsc.in

Annexure I

Price Bid

Date:

To

The Managing Director
Uttar Pradesh Medical Supplies Corporation Ltd,
7/23, sector-7, Gomti Nagar Extension, Lucknow-226002
Phone nos. 0522 2838102

Sub: Notice Inviting Quotations 'for Inspection and repair of Faulty Laptops, Computers (CPU) and UPS from 21.10.23 to 31.10.23 at Uttar Pradesh Medical Supplies Corporation Ltd., Lucknow Headquarters'.

Ref:

Sir.

We quote below our firm prices for Inspection and repair of Faulty Laptops, Computers (CPU) and UPS at Uttar Pradesh Medical Supplies Corporation Ltd., Lucknow Headquarters;

Sr. no.	Ite m Na me	Physic al Inspect ion Comm ents	Part Repair/ Replaceme nt(if any)	Quan tity	Unit Price(I ncl. Of GST)	Service Charges(Incl. GST)	Total Price(I ncl. Of GST)
1.							
2.							
3.							
	Grand Total						
Amou	ınt in Wo	ords:-					

- 1. Quoted rates valid for 90 days from the date of submission of bid.
- 2. I/We accept all the terms and conditions of your Bidding document referred to above.
- 3. I/ We understand you are not bound to accept any proposal you receive.

Signature of the Authorized Signatory:

Name:

Designation:

Name & Address of the Firm:

Uttar Pradesh Medical Supplies Corporation Ltd.

Regd. Office: 7/23, sector-7, Gomti Nagar Extension, Lucknow-226002 Phone nos. 0522 2838102, e-mail:manager.it@upmsc.in

Annexure-II

List of Items for Inspection and Repair

Sr No.	Item Name	Model	Serial No.	Pre-Inspection Remarks
1	CPU	Acer Veriton	UXVQVSI923J3744243	No Display Problem
2	CPU	Acer Veriton	UXBC7SI116J0935148	No Display Problem
3	CPU	HP PRO	4CE8162372	Restart Problem
4	CPU	HP PRO	4CE8162380	HDD Problem
5	CPU	HP PRO	INA812WKD8	HDD Problem
6	UPS	NPS 1000	LI18050134	Battery Problem
7	UPS	NPS 1000	LI18040095	Battery Problem
8	UPS	NPS 1000	LI18040097	Battery Problem
9	UPS	NPS 1000	LI18050126	Battery Problem
10	UPS	NPS 1000	LI18040092	Battery Problem
11	UPS	NPS 1000	LI18050118	Battery Problem
12	UPS	ELNOVA	111191218327	Battery Problem
13	UPS	NPS 1000	LI18050130	Battery Problem
14	UPS	NPS 1000	LI18050123	Battery Problem
15	UPS	ELNOVA	111191217745	Battery Problem
16	UPS	NPS 1000	LI18050112	Battery Problem
17	UPS	NPS 1000	LI18050132	Battery Problem
18	UPS	NPS 1000	LI18040093	Battery Problem
19	UPS	CYBERPOWER	1JV8Q3002063	Battery Problem
20	UPS	CYBERPOWER	1JV9N3001679	Battery Problem
21	UPS	CYBERPOWER	1JV8Q3003445	Battery Problem
22	UPS	CYBERPOWER	1JV8Q3003446	Battery Problem
23	LAPTOP	HP PROBOOK	5CD74674RJ	HDD Problem(Slow Performance
24	LAPTOP	HP PROBOOK	5CD74674FO	HDD Problem(Slow Performance
25	LAPTOP	нр рковоок	5CD74674MS	HDD Problem(Slow Performance